Illinois Commerce Commission Pipeline Safety

Exit Meeting Documentation Form

Operator:	AMEREN ILLINOIS COMPANY
Inspection Unit(s):	Canton
Date of Meeting:	05/21/2015
Pipeline Safety Analyst:	Kevin Hecker, Matt Smith
Exit Meeting Contact:	Dallas Jett

Exit Statement

INSPECTION FINDINGS

Standard Inspection - Field Audit

Issues(s) Found:

[NO ISSUES FOUND]

Notice Of Amendment(s) Found:

[NO NOAS FOUND]

Notice Of Violation(s) Found:

Code Part [192.355(b)(2)] - Staff observed a meter set located under a carport at 1160 E. Locust Street, Canton.

Code Part [192.707(a)(1)] - The casing at the railroad crossing on Route 78 north of Dunfermline was missing a pipeline marker.

Geringtekan (1) 2000 Adva

PAST INSPECTION FINDINGS

Issue(s) Corrected:

[NO ISSUES CORRECTED]

Notice Of Amendment(s) Corrected:

[NO NOAS CORRECTED]

Notice of Violations(s) Corrected:

[NO NOPVS CORRECTED]

Pipeline Safety Analyst Signature:

Operator Representative Signature: